

MIA Recoveries, Inc.
P.O. Box 12871
Prescott, AZ 86304-2871
www.MIArecoveries.org

Crashed Aircraft Site Report

Investigator: Clayton Kuhles

Telephone / E-Mail: 928-899-1614 claytonkuhles@cableone.net

Wreckage: Yes

Model & Serial: B-25D #41-30362

Date Visited: 09 Nov 2011

GPS Coordinates: N 27-22-45.8 E 096-54-14.2

Datum: WGS 84

Country: India

Province / State: Arunachal Pradesh

Nearest Town / Village: Gandhigram

Distance / Directions: 2-day trek NE of Gandhigram.

Map: Google Earth or other satellite imagery.

Elevation: 9,007 ft.

Aspect: W

Topography: Mountains. See photos.

Terrain Notes: Steep, rocky ravine. See photos.

Vegetation: Forest with trees and shrubs. See photos.

Aircraft ID Method: ID tag for Harry D. Tucker with service number 17014288 found at site. See photos.

Engines / Propellers: 2 engines and 2 propellers found at site. See photos.

Wreckage / Artifacts / ID Tags: Wreckage extending approx. 300 yds down ravine from estimated point of impact. Some wreckage on steep, forested slope just N of ravine. ID tag for Harry D. Tucker with service number 17014288 found at site. See photos.

Human Remains: None seen by investigator.

Removed: I removed ID tag for Harry D. Tucker, dead reckoning computer, instruction plate from radio compass and Colt Model 1911 .45 cal automatic pistol. Not known if others removed anything from site. See photos.

Water: Nearest water was .5 mi distant and consisted of a mud bog at highcamp location. Scooped-out holes quickly filled with turbid water. Boiling made water useable. See photos.

Site Disturbance: Some disturbance caused by hydraulic erosion. See photos.

Photos: See website for photos. Additional photos on CD and video on DVD available upon request.

Misc. Notes: